# TerraPi Q Assembly

1. Install the Heat Sink
Place the thermal pads on the heatsink and attach the Pi.

2. Place the SSD mount clips and use the allen key to mount them as shown in the figure A. Do one at a time!

DO NOT OVERTIGHTEN!

A (2:1)

A

A

3. Place the SSD flat on a table.

Mount the SSD clips on the SSD as shown below in FIg. B with M3x6mm screws

C (1.5:1)

B

B (1:1)

C

4. Mount the SSD legs with the M3x4mm screws as shown below in FIg. C

Dept. TECH	Technical reference TPIA-Q	Created by LL 10/25/2020	Approved by LL 25 OCT 2020		
INUX3D design studio		Document type Instructions	Document status FINAL		
		Title TerraPi Q Heat sink Assembly and SSD mount	DWG No. 1		
			Rev. 3	Date of issue 20 OCT 2020	Sheet 1/1